

Under Review Notification

Raised By: Steven Drouin

Product #: D350-589/588

Date: 20.02.03

Product Name: Door Latch

Part Number (D-Part and 9-Digit) (eg. D3535-11) (eg. D3535-25) (eg. D206-642-143) (eg. RBEM324U3010101-1)		"Y" or "N" Required for Each Part Do not leave blank								Reserved ECN / URF Log Number	Instructions Relevant to Each Part (including whether CHG #'s will be affected)
		DO NOT SHIP	Red Tag/Quarantine Stock	Advise Customers	Hold all Production	Quarantine Tooling (Jigs, Fixtures, etc.)	Re-Work Stock	IPP Under Review (Engineer Signoff Required.)	Put Product Specifications Under Review ("Bluefiles")		
D350-589-041	IIN-D350-589 Rev. E	Y	Y	N	Y	Y	Y	N	Y	513	
D350-589-011	IIN-D350-589 Rev. E	Y	Y	N	Y	Y	Y	N	Y	513	
D2586	D2586 Rev. E	Y	Y	N	Y	Y	Y	N	Y	513	Update Drawing
D350-588-041	Iin-D350-588 Rev.D	Y	Y	N	Y	Y	Y	N	Y	513	

Description of Issue:

D2586 needs to be updated to add supplier change, Supplier added a flange in the interior of part, Customer will not be able to install part if update is not done

Distribution:	VP Operations	Director of Engineering	Customer Support Manager	Technical Support
	Director of Operations	Chief Engineer	Production Engineers	Product Manager - Solutions Provider
	Director Quality Assurance	Engineering Project Managers	Production Planners	Supply Chain Director / Senior Buyer
	QC Coordinator	Engineering Clerk	Purchasing Manager	Marketing Eugene